

Waves Water Fun Centre - Blackburn

Waves is a leisure pool with flumes, waves, Jacuzzi, waterfalls and water canon etc. The water treatment was full ozone and sodium hypochlorite and carbon dioxide for pH correction. From opening it experienced severe corrosion difficulties with stainless steel fittings, and air handling units. The corrosion was so severe that major refurbishment of the air handling had to be carried out in 1990. Stainless steel hand rails had to have rust cleaned off every week.



The POOLCURE System replaced the ozone system in 1990.

The POOLCURE System saved more than twice its annual running cost in the first year.

- The sodium hypochlorite usage was halved.
- Carbon dioxide usage was reduced by 90%.
- Total Dissolved Solids was reduced.
- British Steel Stainless carried out monitoring of corrosion from 1989 and confirmed that corrosion ceased when POOLCURE was used.

Total Pool Chemicals Ltd
Unit 5 Pool Bank Business Park
High Street
Tarvin
Chester
CH3 8JH
01829 740290
www.totalpoolchemicals.co.uk
Email: sales@totalpoolchemicals.co.uk